

**Flood Control Project Maintenance  
Levee Inspections**

## Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2015

### Sacramento Maintenance Yard East Levee Yolo Bypass

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Yolo Bypass	Left	2.01	04/15/2015 04/15/2015	Jai Lor

LM Start		Rating **	A	Issue No.	3
LM End		Issue Type +	Ma	Location *	N/A
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Operations & Maintenance Manuals			°	°
				°	°
DWR ID	DWR_ST0004_01_s _ 2013_3				
Action/Comments					
Inspector Comments: The Sacramento Maintenance Yard has the levee manuals.					

No Photos

LM Start		Rating **	A	Issue No.	4
LM End		Issue Type +	Ma	Location *	N/A
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Emergency Supplies & Equipment			°	°
				°	°
DWR ID	DWR_ST0004_01_s _ 2013_4				
Action/Comments					
Inspector Comments: The Sacramento Maintenance Yard maintains a stockpile of flood response material.					

No Photos

LM Start		Rating **	A	Issue No.	5
LM End		Issue Type +	Ma	Location *	N/A
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Flood Preparedness & Training			°	°
				°	°
DWR ID	DWR_ST0004_01_s _ 2013_5				
Action/Comments					
Inspector Comments: The Sacramento Maintenance Yard has a written response plan and regular flood response training.					

No Photos

<b>* Location</b> LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance  
Levee Inspections**

## Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2015

### Sacramento Maintenance Yard East Levee Yolo Bypass

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Yolo Bypass	Left	2.01	04/15/2015 04/15/2015	Jai Lor

LM Start	0.01	Rating **	M	Issue No.	102	
LM End	2.01	Issue Type +	Ma	Location *	LS	
Category	Earthen Levee			GPS Latitude/Longitude		
				Start		End
Item	Vegetation			38.765307 °		°
				-121.635208 °		°
DWR ID	DWR_ST0004_01_s_2015_102					
Action/Comments						
Control annual grass and weeds on the levee slopes and easements.						

Photo 1 of 1 : SP\_2015\_ST0004\_41\_102\_20150415\_00001.jpg



View of the vegetation on the landward side of the levee looking downstream. Spring 2015.

LM Start	0.19	Rating **	M	Issue No.	103	
LM End	2.01	Issue Type +	Ma	Location *	WS	
Category	Earthen Levee			GPS Latitude/Longitude		
				Start	End	
Item	Vegetation			38.762587 °		°
				-121.635423 °		°
DWR ID	DWR_ST0004_01_s_2015_103					
Action/Comments						
Control annual grass and weeds on the levee slopes and easements.						

No Photos

LM Start	1.68	Rating **	M	Issue No.	104
LM End	2.02	Issue Type +	Ma	Location *	CR
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Crown Surface / Depressions / Rutting			38.741080 °	38.736103 °
				-121.634018 °	-121.633682 °
DWR ID	DWR_ST0004_01_s_2015_104				
Action/Comments					
Add appropriate gravel or road base. Grade and compact.					

Photo 1 of 1 : SP\_2015\_ST0004\_41\_104\_20150415\_00002.jpg



View of the depression on the crown of the levee looking downstream. Spring 2015.

<b>* Location</b>		<b>** Rating</b>		<b>+ Issue Type</b>	
LS : Land Side	N/A : Not Applicable	A : Acceptable	N : Not Inspected/Rated	Ma : Maintenance Deficiency	
WS : Water Side		M : Minimally Acceptable	C : Corrected	Ob : Design & System Obsolescence	
CR : Crown		U : Unacceptable	A/W : Acceptable but Monitor & Maintain	En : Enforcement	